

Welding-Question 4

Name the different thermal and mechanical Cutting methods.

1. Gas Metal Arc Welding (GMAW)
2. Gas Tungsten Arc Welding (GTAW)
3. Shielded Metal Arc Welding (SMAW)
4. Flux cord arc welding (FCAW)
5. Plasma Arc Welding (PAW)
6. Electron beam welding
7. Laser beam welding
8. Oxy-Fuel Welding (OFW)
9. Submerged Arc Welding (SAW)
10. Electroslag welding
- 11 Resistance Welding
- 12 Oxy-Fuel Brazing (OFB)